


General Information

Date & Time: 01, Mar, 2024 13:16

Make	Suzuki	Model	Other
YOM	2018	Mileage	189,816
Registration No.	BPN-847	Chassis No.	10038424
CC	undefined	Transmission	Manual
Fuel Type	Petrol	Type of Body	Hatchback
Colour	White	Grade	undefined
Expiry Revenue license	06-04-2024	Expiry Insurance	06-04-2024

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	5.3	4	5	7
2	Boot Lid	3.8	4	4	4
3	Roof	2.5	4	4	2/1
4	Left Front Fender	3.1	4	1	5
5	Left Front Door	3.0	4	1	4
6	Center Panel Left				
7	Left Rear Door	3.4	4	3	4
8	Left Back Panel	4.2	4	4	5
9	Right Front Fender	3.8	4	4	4
10	Right Front Door	3.9	4	4	4
11	Center Panel Right				
12	Right Rear Door	2.5	0	3	4
13	Right Back Panel	4.3	4	4	4

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Steering Wheel - Worn, Peel, Crack - Medium / Right Front Floor Lag - Cut, Crack - Medium / Left Front Floor Lag - Cut, Crack - Medium / Console - Loose, Deformed, Grime - Medium / Right Front Seat - Fray - Minimal / Right Rear Trim - Grime - Minimal / Rear Seat - Grime - Minimal / Trunk Room - Loose, Deformed, Grime - Large / Left Front Seat - Grime - Minimal / Left Front Trim - Grime - Medium</p>	<p>Remarks Right Front Door - Repair Traces - Yes / Right Step and Side Spoiler - Repair Traces - Yes / Right Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / Left Front Fender - Repair Traces - Yes / Left Front Door - Repair Traces - Yes / Left Step and Side Spoiler - Repair Traces - Yes / Left Rear Door - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Rear End Panel - Repair Traces - Yes / Right Rear Door - Repair Traces - Yes / Right Front Fender - Scratch - Small / Right Front Door - Rust, Corrosion - Small / Right Rear Door - Rust, Corrosion - Medium / Right Rear Fender - Dent - Small / Left Front Fender - Rust, Corrosion - Medium / Left Rear Door - Scratch - Large / Left Front Door - Scratch - Large / Left Rear Fender - Rust, Corrosion - Large / Front Bumper and Grille - Scratch - Large / Bonnet, Headlight - Dent - Minimal / Roof - Dent - Small / Trunk Hood, Rear Gate - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large</p>
Frame Evaluation : B-	Functional Evaluation : B-
<p>Remarks Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes / Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Retractable Mirror - Issue - Yes / Panel, Meter - Issue - Yes / Door Lock - Issue - Yes / Battery - Weak - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

Inspector Notes