


General Information

Date & Time: 02, Mar, 2024 10:26

Make	Suzuki	Model	Other
YOM	2019	Mileage	222,130
Registration No.	LEH-19-4991	Chassis No.	NF1AVK31H10047940
CC	undefined	Transmission	Manual
Fuel Type	Petrol	Type of Body	Hatchback
Colour	White	Grade	undefined
Expiry Revenue license	06-04-2024	Expiry Insurance	06-04-2024

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	3.8	4	5	3
2	Boot Lid	3.1	3	3	3
3	Roof	3.1	3	3	3/3
4	Left Front Fender	3.5	4	3	4
5	Left Front Door	3.3	4	3	3
6	Center Panel Left				
7	Left Rear Door	3.3	4	3	3
8	Left Back Panel	3.7	4	4	3
9	Right Front Fender	2.9	3	3	3
10	Right Front Door	2.8	3	3	3
11	Center Panel Right				
12	Right Rear Door	2.9	3	3	3
13	Right Back Panel	3.1	3	3	3

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B+
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Crinkle - Small / Carpet - Loose, Deformed, Grime - Small / Right Front Floor Lag - Loose, Deformed, Grime - Medium / Left Front Floor Lag - Loose, Deformed, Grime - Small / Right Front Seat - Cut, Crack - Medium / Trunk Room - Loose, Deformed, Grime - Medium</p>	<p>Remarks Right Step and Side Spoiler - Repair Traces - Yes / Right Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / Left Front Fender - Repair Traces - Yes / Left Step and Side Spoiler - Repair Traces - Yes</p>
Frame Evaluation : B	Functional Evaluation : C
<p>Remarks Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes</p>	<p>Remarks Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Wiper - Function - Weak</p>

<p>Inspector Notes</p>