


General Information

Date & Time: 29, Feb, 2024 17:14

Make	Toyota	Model	Corolla
YOM	2014	Mileage	187,024
Registration No.	LED-14-2334	Chassis No.	ZRE172R-7001517
CC	undefined	Transmission	Automatic
Fuel Type	Petrol	Type of Body	Sedan/Saloon
Colour	White	Grade	undefined
Expiry Revenue license		Expiry Insurance	

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	5.5	5	6	6
2	Boot Lid	4.8	5	4	5
3	Roof	4.6	5	4	5/5
4	Left Front Fender	4.8	5	5	5
5	Left Front Door	18.2	9	12	34
6	Center Panel Left				
7	Left Rear Door	16.6	30	9	11
8	Left Back Panel	5.8	5	7	6
9	Right Front Fender	8.0	6	7	12
10	Right Front Door	4.5	4	5	5
11	Center Panel Right				
12	Right Rear Door	4.8	5	5	5
13	Right Back Panel	7.2	5	5	11

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Instrument Panel - Worn, Scratch, Cut, Crack - Minimal / Carpet - Worn, Scratch, Cut, Crack - Small / Right Front Seat - Cut, Crack - Small / Right Front Trim - Cut, Crack - Small / Rear Seat - Grime - Minimal / Trunk Room - Loose, Deformed, Grime - Small / Left Front Seat - Grime - Minimal</p>	<p>Remarks Left Front Door - Repair Traces - Yes / Left Rear Door - Repair Traces - Yes / Right Rear Door - Repair Traces - Yes / Right Front Fender - Scratch - Minimal / Supplemental Mirror - Scratch, Peeled - Yes / Right Front Door - Scratch - Minimal / Right Rear Door - Scratch - Small / Right Rear Fender - Scratch - Minimal / Left Front Door - Scratch - Minimal / Left Rear Door - Scratch - Small / Front Bumper and Grille - Scratch - Small / Bonnet, Headlight - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal</p>
Frame Evaluation : B+	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Wiper - Function - Weak</p>

Inspector Notes