


General Information

Date & Time: 02, Mar, 2024 09:47

Make	Suzuki	Model	Other
YOM	2007	Mileage	191,100
Registration No.	LEA-07-9923	Chassis No.	372949
CC	undefined	Transmission	Manual
Fuel Type	Petrol	Type of Body	Hatchback
Colour	White	Grade	undefined
Expiry Revenue license	06-04-2024	Expiry Insurance	06-04-2024

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	6.1	7	6	6
2	Boot Lid	10.9	8	16	9
3	Roof	4.1	4	5	4/4
4	Left Front Fender	2.9	3	3	3
5	Left Front Door	10.0	10	8	12
6	Center Panel Left				
7	Left Rear Door	21.2	12	13	39
8	Left Back Panel	6.0	6	6	6
9	Right Front Fender	5.8	8	5	5
10	Right Front Door	16.9	20	15	16
11	Center Panel Right				
12	Right Rear Door	3.3	3	3	4
13	Right Back Panel	3.7	4	4	4

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B-	Exterior Evaluation : B+
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Room Lamp - Stuck - Yes / Switches - Missing - Yes / Steering Wheel - Worn, Peel, Crack - Medium / Carpet - Loose, Deformed, Grime - Medium / Right Front Floor Lag - Loose, Deformed, Grime - Medium / Left Front Floor Lag - Loose, Deformed, Grime - Small / Right Front Trim - Worked - Small / Trunk Room - Loose, Deformed, Grime - Small / Left Front Trim - Loose, Deformed, Grime - Small / Left Rear Trim - Loose, Deformed, Grime - Small</p>	<p>Remarks Defects not found</p>
Frame Evaluation : B+	Functional Evaluation : B-
<p>Remarks Defects not found</p>	<p>Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Seat Belts - Issue - Yes</p>

<p>Inspector Notes</p>