


General Information

Date & Time: 29, Feb, 2024 12:12

Make	Toyota	Model	Corolla
YOM	2021	Mileage	67,122
Registration No.	AHB-090	Chassis No.	ZRE171R-6063732
CC	1.6	Transmission	Automatic
Fuel Type	Petrol	Type of Body	Sedan/Saloon
Colour	Black	Grade	undefined
Expiry Revenue license		Expiry Insurance	

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	167.3	129	206	167
2	Boot Lid	110.6	102	125	105
3	Roof	113.2	112	119	107/115
4	Left Front Fender	156.6	152	149	169
5	Left Front Door	140.0	140	144	136
6	Center Panel Left				
7	Left Rear Door	137.3	136	138	138
8	Left Back Panel	175.0	132	233	160
9	Right Front Fender	124.6	122	126	126
10	Right Front Door	136.6	140	142	128
11	Center Panel Right				
12	Right Rear Door	118.2	78	149	128
13	Right Back Panel	145.0	119	146	170

Overall Evaluation :

B+

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation :	B+	Exterior Evaluation :	B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Console - Loose, Deformed, Grime - Minimal / Right Front Seat - Grime - Minimal / Rear Seat - Grime - Minimal / Left Front Seat - Grime - Minimal</p>		<p>Remarks Bonnet - Repair Traces - Yes / Left Rear Fender - Repair Traces - Yes / Right Rear Door - Repair Traces - Yes / Right Front Fender - Scratch - Minimal / Right Front Door - Dent - Minimal / Right Rear Door - Dent - Minimal / Right Rear Fender - Dent - Small / Left Front Door - Scratch - Small / Right Step and Side Spoiler - Scratch - Small / Trunk Hood, Rear Gate - Dent - Minimal / Front Bumper and Grille - Scratch - Minimal</p>	
Frame Evaluation :	B+	Functional Evaluation :	B+
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	

Inspector Notes