


General Information

Date & Time: 02, Mar, 2024 10:58

Make	Toyota	Model	Corolla
YOM	2009	Mileage	343,388
Registration No.	LED-09-6234	Chassis No.	NZE1402030342
CC	undefined	Transmission	Manual
Fuel Type	Petrol	Type of Body	Sedan/Saloon
Colour	Gray	Grade	undefined
Expiry Revenue license	06-04-2024	Expiry Insurance	06-04-2024

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	6.1	4	4	10
2	Boot Lid	8.0	8	8	8
3	Roof	10.6	15	8	8/11
4	Left Front Fender	34.1	29	33	40
5	Left Front Door	31.4	27	32	36
6	Center Panel Left				
7	Left Rear Door	38.3	26	47	41
8	Left Back Panel	16.3	18	16	16
9	Right Front Fender	13.0	12	11	17
10	Right Front Door	13.6	15	12	14
11	Center Panel Right				
12	Right Rear Door	16.3	21	15	13
13	Right Back Panel	23.9	25	23	24

Overall Evaluation :

B-

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B-	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Crinkle - Medium / Dashboard - Loose, Deformed, Grime - Medium / Console - Loose, Deformed, Grime - Medium / Carpet - Worn, Scratch, Cut, Crack - Minimal / Right Front Seat - Worn - Yes / Right Front Trim - Grime - Minimal / Left Front Trim - Grime - Minimal / Right Rear Trim - Grime - Minimal / Left Rear Trim - Grime - Minimal / Rear Seat - Grime - Medium / Trunk Room - Loose, Deformed, Grime - Minimal / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Left Front Seat - Cigarette Burns - Burnt Minimal</p>	<p>Remarks Right Front Door - Scratch - Small / Right Rear Door - Scratch - Large / Right Rear Fender - Rust, Corrosion - Small / Trunk Hood, Rear Gate - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / Roof - Dent - Minimal / Bonnet, Headlight - Dent - Minimal / Front Bumper and Grille - Scratch - Large / Left Rear Door - Scratch - Medium / Left Front Door - Scratch - Medium</p>
Frame Evaluation : B+	Functional Evaluation : B-
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Wiper - Function - Weak</p>

<p>Inspector Notes</p>