


## General Information

Date & Time: 28, Feb, 2024 18:45

<b>Make</b>	Kia	<b>Model</b>	Other
<b>YOM</b>	2021	<b>Mileage</b>	19,002
<b>Registration No.</b>	AGZ-664	<b>Chassis No.</b>	KNHNC374MN6142765
<b>CC</b>	undefined	<b>Transmission</b>	Automatic
<b>Fuel Type</b>	Petrol	<b>Type of Body</b>	MPV
<b>Colour</b>	White	<b>Grade</b>	undefined
<b>Expiry Revenue license</b>		<b>Expiry Insurance</b>	

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	5.8	6	6	6
2	Boot Lid	5.2	5	5	6
3	Roof	5.6	5	5	6/6
4	Left Front Fender	7.2	9	8	5
5	Left Front Door	5.6	6	6	5
6	Center Panel Left				
7	Left Rear Door	5.6	6	6	5
8	Left Back Panel	6.2	6	6	7
9	Right Front Fender	5.4	5	6	5
10	Right Front Door	3.5	4	1	6
11	Center Panel Right				
12	Right Rear Door	12.6	6	27	6
13	Right Back Panel	8.9	7	6	14

Overall Evaluation :

**B+**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B+</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Defects not found	<b>Remarks</b> Right Front Door - Scratch - Minimal / Right Rear Door - Dent - Small / Left Front Door - Scratch - Minimal / Bonnet, Headlight - Dent - Medium / Front Bumper and Grille - Scratch - Small
<b>Frame Evaluation :</b> <span style="float: right;"><b>B+</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B+</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found

<b>Inspector Notes</b>