


General Information

Date & Time: 02, Mar, 2024 10:04

Make	Toyota	Model	Land Cruiser Prado
YOM	2019	Mileage	27,521
Registration No.	AQR-911	Chassis No.	TRJ150-0107632
CC	2.7	Transmission	Automatic
Fuel Type	Petrol	Type of Body	SUV / 4x4
Colour	White	Grade	undefined
Expiry Revenue license	06-04-2024	Expiry Insurance	06-04-2024

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	11.9	12	12	12
2	Boot Lid	12.4	12	13	13
3	Roof	18.5	13	37	13/13
4	Left Front Fender	12.3	12	12	12
5	Left Front Door	12.6	13	13	13
6	Center Panel Left				
7	Left Rear Door	12.4	13	12	12
8	Left Back Panel	12.5	12	12	13
9	Right Front Fender	11.9	12	12	12
10	Right Front Door	12.4	12	13	12
11	Center Panel Right				
12	Right Rear Door	13.8	17	12	12
13	Right Back Panel	12.7	13	13	13

Overall Evaluation :

B+

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B+	Exterior Evaluation : B+
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks Defects not found
Frame Evaluation : B+	Functional Evaluation : B+
Remarks Defects not found	Remarks Defects not found

Inspector Notes