


General Information

Date & Time: 15, Feb, 2024 17:12

Make	Toyota	Model	Corolla
YOM	2019	Mileage	62,085
Registration No.	BQG-844	Chassis No.	ZRE171R6036837
CC	1.6	Transmission	Manual
Fuel Type	Petrol	Type of Body	Sedan/Saloon
Colour	White	Grade	undefined
Expiry Revenue license	22-03-2024	Expiry Insurance	23-03-2024

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	5.0	6	5	5
2	Boot Lid	4.2	4	5	4
3	Roof	3.0	4	0	4/4
4	Left Front Fender	5.0	5	6	4
5	Left Front Door	5.0	5	5	5
6	Center Panel Left				
7	Left Rear Door	19.1	26	19	12
8	Left Back Panel	10.2	14	10	8
9	Right Front Fender	6.7	4	5	11
10	Right Front Door	9.9	1	5	24
11	Center Panel Right				
12	Right Rear Door	4.0	3	5	5
13	Right Back Panel	4.6	6	3	5

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B+
<div style="text-align: center;">  </div> <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<div style="text-align: center;">  </div> <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Steering Wheel - Worn, Peel, Crack - Medium / Right Front Floor Lag - Missing - Yes / Right Front Seat - Grime - Medium / Left Front Seat - Grime - Medium / Console - Worn, Scratch, Cut, Crack - Medium / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Medium / Right Front Trim - Grime - Medium / Left Front Trim - Grime - Small / Left Rear Trim - Grime - Medium</p>	<p>Remarks Left Rear Door - Repair Traces - Yes</p>
Frame Evaluation : B+	Functional Evaluation : B+
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>left side rear door paint marks</p>